



MANDATORY SERVICE BULLETIN Z 142/54a – Supplement 1

„SAFETY RELATED“

Technical content of the document is approved
on the basis of DOA Approval No. EASA.21J.110

- 1. DATE:** February 28, 2018

- 2. APPLICABLE TO:** *All Z 142 aircraft with unstrengthened wings (i.e. aircraft on which the wings replacement for strengthened wings acc. to MSB Z142/43a or Z142/50a or Z142/55a has not been performed).*

- 3. REASON:** **Based on the manufacturer decision the possibility of root wing part reconstruction with pertinent prolongation of total safe life from 3600 hours to 4800 hours TIS was cancelled.**
 - 4.2 Aircraft safe life time prolongation from 3600 to 4800 hours TIS.**

Performing of root wing part reconstruction for Z 142 aircraft in operation is not possible.

- 8. PROCEDURES:** Print this supplement No. 1 and insert it in the bulletin Z 142/54a with date of issue March 8, 2007.

ZLIN AIRCRAFT

Letiště 1887
765 02 Otrokovice

www.zlinaircraft.eu



Prepared by:

.....
Lubomír Januška

Head of Documentation and Normalization Dpt.

Approved by:

.....
Ing. Miloslav Tutter

Head of DOA