

**MANDATORY SERVICE BULLETIN Z143LSi/8a**

Technical content of the document approved  
on the basis of DOA Authority No. EASA.21J.110

1. **DATE:** February 14, 2013
2. **MODEL AFFECTED:** All Z 143 LSi aircraft
3. **SUBJECT:** Incorporation of formal, grammar and edit corrections and correction of mistakes in Z 143 LSi Aircraft Flight Manual found during aircraft operation.  
**Technical content and factual form of document has not been changed.**
4. **CORRECTION:** Issue of revision No. 3 of Z 143 LSi Aircraft Flight Manual (č. dok. Si005.011 czech version), (Doc. No. Si005.012 english version).
5. **TIME OF COMPLIANCE:** Immediately after receipt of bulletin.
6. **PERFORMED BY:** Operator.
7. **COSTS COVERED BY:** No will arise.
8. **PROCEDURES:**
  - a) In Z 143 LSi Aircraft Flight Manual (č. Dok. Si005.011) - czech version:
    - Remove all pages of flight manual
    - Insert new pages marked with Revision No. 3 with date of issue 14.2.2013.
    - Re-write aircraft serial number and registration mark to title page
    - Note this revision into the List of Revision.
  - b) In Z 143 LSi Aircraft Flight Manual (Doc. No. Si005.012) - english version:
    - Remove all pages of flight manual
    - Insert new pages marked with Revision No. 3 with date of issue 14.2.2013.
    - Re-write aircraft serial number and registration mark to title page
    - Note this revision into the List of Revision

**9. NECESSARY MATERIAL:** New pages of Z 143 LSi Aircraft Flight Manual (č. dok. Si005.011 czech version), (Doc. No. Si005.012 english version).

**10. ENCLOSURES:** New pages of Z 143 LSi Aircraft Flight Manual (č. dok. Si005.011 czech version), (Doc. No. Si005.012 english version) with Revision No. 3 with date of issue 14.2.2013 is available for free on the web sites of the manufacturer to all holders of “bulletin service”.



.....  
**Dušan Totek**  
Chief Designer

**Contact address:** ZLIN AIRCRAFT a.s.  
765 02 Otrokovice  
Czech Republic