

## MANDATORY SERVICE BULLETIN No. Z 242L/70a

SAFETY RELATED

The technical content of this document is approved on the basis of the DOA Approval No.: EASA.21J.110.

1. DATE

May 6, 2024.

2. SUBJECT:

Vertical pin damage P/N Z 42.2181-00.00

3. MODEL AFFECTED:

Airplanes Z 242 L operated by Sault College Aviation

Technology Inc.:

S/N 0681 C-FANU S/N 0682 C-FHTU S/N 0684 C-FCSB S/N 0685 C-FVWT S/N 0742 C-GHXG S/N 0743 C-GSOP S/N 0744 C-GERR S/N 0745 **C-GHXF** S/N 0746 C-GJOR

which are operated in the UTILITY and NORMAL category with an individually extended technical life of the airframe beyond the approved period of 5500 hours in service, and

S/N 0699 C-FZHF S/N 0727 C-GLKU S/N 0739 C-FSCZ

which are operated to the full range of the airworthiness categories within the basic approved technical lifetime of 5500 hours in service.



4. REASON:

Repeatedly recorded failures of vertical pins P/N Z42.2181-00.00 for aircraft S/Ns 0746 and 0681 and based on demonstrable misconduct by the operator's maintenance organization in performing the maintenance prescribed by the aircraft TC holder, focusing on the identification, use and correct procedure of replacing vertical and horizontal pins using the prescribed tools and fixtures.

5. REQUIRED ACTION:

The Z 242 L aircraft manufacturer and aircraft type certificate holder ZLIN AERO a.s. hereby issues an order for the temporary shutdown operation of the abovementioned aircraft.

The planes are not airworthy, and the safety of their operation is not ensured.

6. TIME OF COMPLIANCE: Immediately upon receipt of this bulletin.

7. **PERFORMED BY:** Operator.

**8. COSTS COVERED BY:** Operator.

9. PROCEDURES: Until the matter is resolved, and an optimal solution

proposed to fully restore airworthiness, stop the operation

of the above-mentioned airplanes.

Immediately carry out the required actions specified in the

Service Letter L148, point 2) dated 4/30/2024.

Insert this Mandatory Service Bulletin in the on-board documentation of the aircraft serial numbers applied.

Record the execution of this service bulletin in the

aircraft's operating and maintenance documentation.

10. NECESSARY MATERIAL: None.

11. ENCLOSURES: None.

Prepared by:

Lubomír Januška

Head of Documentation and Standardization Department



Approved by:

Ing. Martin Kotačka Head of Airworthiness Office