



MANDATORY SERVICE BULLETIN Z 42/55a – Supplement 1

„SAFETY RELATED“

Technical content of the document is approved
on the basis of DOA Approval No. EASA.21J.110

- 1. DATE:** February 28, 2018

- 2. APPLICABLE TO:** *All Z 42M, Z 42MU aircraft with unstrengthened wings (i.e. aircraft on which the wings replacement for strengthened wings acc. to MSB Z42/46a or Z42/52a or Z42/56a has not been performed).*

- 3. REASON:** **Based on the manufacturer decision the possibility of root wing part reconstruction with pertinent prolongation of total safe life from 3600 hours to 4800 hours TIS was cancelled.**

4.2 Aircraft safe life time prolongation from 3600 to 4800 hours TIS.
Performing of root wing part reconstruction for Z 42M, Z 42MU aircraft in operation is not possible.

- 8. PROCEDURES:** Print this supplement No. 1 and insert it in the bulletin Z 42/55a with date of issue March 8, 2007.

ZLIN AIRCRAFT

Letiště 1887
765 02 Otrokovice

www.zlinaircraft.eu



Prepared by:

.....
Lubomír Januška

Head of Documentation and Normalization Dpt.

Approved by:

.....
Ing. Miloš Tutter

Head of DOA