Download date: 14.03.2013



## ZLIN AIRCRAFT a.s.

Letiště 1578, 765 81 Otrokovice, Czech Republic

e-mail: zlinservice@zlinaircraft.eu http://www.zlinaircraft.eu



## MANDATORY SERVICE BULLETIN No. Z 142/32a

1. MODELS AFFECTED:

All Z 142 aircraft

2. SUBJECT:

the V 500 P 7900-611 Increased stress of propeller flange, caused by the execution of power, must be engine spins with the prevented.

3. CORRECTION:

1. Prohibition of intentional power on spins.

2. Replacement of pages in the Airplane Flight

Manual.

4. TIME OF COMPLIANCE:

Immadiately after the Bulletin receipt.

5. CORRECTION PERFORMED BY: The user.

6. EXPENSES COVERED BY: No expenses will arise.

MATERIAL: New pages of the Z 142 AFM dated from August

31, 1995 are enclosed to this Bulletin.

8. PROCEDURE:

7. NECESSARY

Replace original pages by the new ones revision into the Record of enter this

revisions.

IS EFFECTIVE FROM THE DATE OF APPROVAL BY THE CIVIL 9. THIS BULLETIN AVIATION INSPECTORATE.

10. ENCLOSURES:

New pages of the Z 142 AFM:

2-11/2-12

artika

Manufacturer's Representative Milan Vyhnálek .......

CAI Representative

Date of approval by the CAI

CONTACT ADDRESS:

ZLIN AIRCRAFT a.s.

ZLIN Service

765 81 OTROKOVICE CZECH REPUBLIC