

ZLIN AIRCRAFT a.s. Letiště 1578, 765 81 Otrokovice, Czech Republic

e-mail: zlinservice@zlinaircraft.eu http://www.zlinaircraft.eu



MANDATORY SERVICE BULLETIN Z 142/38a

Engineering Aspects are CAA of CR Approved

1. DATE: January 16, 1998

2. MODELS AFFECTED: All Z 142 aircraft.

3. SUBJECT: The RPM indicator colour marking, defined in the Flight Manual, is

not fully identical with the actual colour marking of the

LUN 1341.2-8 or LUN 1345.2-8 RPM indicator.

The yellow arc on this RPM indicator is indicated in the range of 2680 - 2860 rpm. The Flight Manual states the range of 2600 -

2860 rpm.

4. CORRECTION: Correction of the RPM indicator colour marking in the Flight

Manual.

5. TIME OF Immediately after the Bulletin receipt.

COMPLIANCE:

6. CORRECTION The Operator of aircraft

PERFORMED BY:

COVERED BY:

7. EXPENSES

Not applicable

8. PROCEDURE: Replace old pages by new ones dated Jan 16, 1998 in the

appropriate Flight Manuals:

Download date: 14.03.2013

MANDATORY SERVICE BULLETIN Z 142/38a

The Czech version:

Letová příručka Z 142: pages 2-5/2-6

The German version:

Flughandbuch Z 142: pages 2-5/2-6

The English version:

Z 142 Flight Manual: pages 2-5/2-6

The French version:

Manuel de vol de l'avion Z 142: pages 2-5/2-6

Enter and confirm the revision into the Log of Revisions.

9. NECESSARY MATERIAL:

New pages of appropriate Flight Manuals will be delivered by the

Manufacturer along with the Bulletin.

10. **ENCLOSURES**: In accordance with point 9 of this Bulletin.

Dipl. Eng. Josef Kolář

Manufacturer's Representative

Contact adress: ZLIN AIRCRAFT a.s.

ZLIN Service

765 81 OTROKOVICE CZECH REPUBLIC