



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 143L/27a

Engineering aspects are
CAA CZ approved

- 1. DATE:** May 18, 2004
- 2. MODEL AFFECTED:** All Z 143 L aircraft
- 3. SUBJECT:** Permission of max. six-turn spins performance in Utility category according to FAR Part 23.3 (b) (1) regulation.
- 4. CORRECTION:** Relevant revision of Flight Manual of the Z 143 L aircraft.
Replacement of relevant placard in the cabin.
- 5. TIME COMPLIANCE:** Immediately after receipt of the bulletin.
- 6. PERFORMED BY:** Operator.
- 7. COST COVERED BY:** No will arise.
- 8. PROCEDURES:**

In the Flight Manual of the Z 143 L, DOC. No. 005.012US:

 - Remove old pages:
0-1; 0-9; 0-10; 0-14; 2-13; 2-14; 2-20; 4-31; 4-32
 - Insert new pages marked with Revision. No. 5 with date May 18, 2004 (see Enclosure).
 - Note this revision into the list of revisions.
 - Replace limitations placard located on the canopy glass - placard No. (1) from the Flight Manual, para. 2.16.1 (page 2-20).

In the Flight Manual of the Z 143 L, DOC. No. 005.012:

 - Remove old pages:
0-1; 0-9; 0-10; 0-15; 2-14; 2-20; 4-31
 - Insert new pages marked with Revision. No. 10 with date May 18, 2004 (see Enclosure).
 - Note this revision into the list of revisions.
 - Replace limitations placard located on the canopy glass - placard No. (1) from the Flight Manual, para. 2.16.1 (page 2-20).

MANDATORY SERVICE BULLETIN Z 143L/27a

In the Flight Manual of the Z 143 L, DOC. No. 005.011:

- Remove old pages:
0-1; 0-9; 0-10; 0-15; 2-13; 2-19; 4-27
- Insert new pages marked with Revision. No. 10 with date May 18, 2004 (see Enclosure).
- Note this revision into the list of revisions.
- Replace limitations placard located on the canopy glass - placard No. (1) from the Flight Manual, para. 2.16.1 (page 2-19).

In the Maintenance Manual of the Z 143L, DOC. No. 005.021.1:

- Remove old pages:
01-11, 01-13, 01-35, 11-13, 11-14
- Insert new pages marked with Revision. No. 7 with date May 18, 2004 (see Enclosure).
- Note this revision into the list of revisions.

In the Maintenance Manual of the Z 143L, DOC. No. 005.022.1:

- Remove old pages:
01-11, 01-13, 01-35, 11-13, 11-14
- Insert new pages marked with Revision. No. 7 with date May 18, 2004 (see Enclosure).
- Note this revision into the list of revisions.

9. NECESSARY MATERIAL: New pages of Flight Manual of the Z 143 L aircraft, US version, DOC. No. 005.012US and new limitations placard – see Enclosure.

New pages of Flight Manual of the Z 143 L aircraft, english version, DOC. No. 005.012 and new limitations placard – see Enclosure.

New pages of Flight Manual of the Z 143 L aircraft, czech version, DOC. No. 005.011 and new limitations placard – see Enclosure.

New pages of Maintenance Manual of the Z 143 L aircraft, czech version, DOC. No. 005.021.1.

New pages of Maintenance Manual of the Z 143 L aircraft, english version, DOC. No. 005.022.1.

10. ENCLOSURES: New pages of the Z 143 L Flight Manual, US version, DOC. No. 005.012US:
0-1; 0-9; 0-10; 0-14; 2-13; 2-14; 2-20; 4-31; 4-32; 4-32a; 4-32b; 4-34a; 4-34b

New pages of the Z 143 L Flight Manual, english version,
DOC. No. 005.012:
0-1; 0-9; 0-10; 0-15; 2-14; 2-20; 4-31

New pages of the Z 143 L Flight Manual, czech version,
DOC. No. 005.011:
0-1; 0-9; 0-10; 0-15; 2-13; 2-19; 4-27

New pages of the Z 143 L Maintenance Manual, czech version,
DOC. No. 005.021.1.
01-11, 01-13, 01-35, 11-13, 11-14

New pages of the Z 143 L Maintenance Manual, english
version, DOC. No. 005.022.1.
01-11, 01-13, 01-35, 11-13, 11-14

New limitations placard - placard No. (1) from the Flight
Manual, para. 2.16.1 .



.....
Ing. Dušan Totek
Chief designer

Contact address: ZLIN AIRCRAFT a.s.
ZLIN service
765 81 Otrokovice
Czech Republic