



**ZLIN AIRCRAFT a.s.**  
Letiště 1578, 765 81 Otrokovice,  
Czech Republic  
e-mail: [zlin-service@zlinaircraft.eu](mailto:zlin-service@zlinaircraft.eu)  
<http://www.zlinaircraft.eu>

**MANDATORY**

**SERVICE  
BULLETIN**

**MANDATORY SERVICE BULLETIN Z 42/60a**

**Z 142/59a**

**Z 142C/35a**

**Z 142C-AF/16a**

**Z 242L/58a**

Technical content of the document is approved  
on the basis of DOA Approval No. EASA.21J.110

- 1. DATE:** May 6, 2010
- 2. APPLICABLE TO:** All Z 42M, Z 42MU, Z 142, Z 142C, Z 142C-AF, Z 242L aircraft equipped with the AMU1 Acceleration Monitoring Unit.
- 3. REASON:** Issue of revised documentation “AMU1.01 Acceleration Monitoring Unit Maintenance and Repair Manual“, Doc. No. Z42.AMU1.071, date of issue 1.5.2010.  
The manual is available only for authorized persons of authorized service organization or aircraft manufacturer for installation and repairs of the AMU1.01 Acceleration Monitoring Unit.
- 4. ACTIONS REQUIRED:** Issue of revised accompanying documentation.
- 5. ACCOMPLISHMENT:** According to operator/owner decision
- 6. PERFORMED BY:** Operator/owner.
- 7. COSTS COVERED BY:** Operator/owner.
- 8. PROCEDURES:** In case that you own any previous version of the manual, please be aware that based on this bulletin previous versions of the manual are no more valid and will be no more revised. It is necessary to order the new manual.  
It is not possible to perform installation and connection of the AMU1.01 Acceleration Monitoring Unit without buying a new registered copy of the manual!

**9. NECESSARY MATERIAL:** The manual will be sent for payment on the basis of written order on condition that instructional course will be completed.

**10. ENCLOSURES:** N/A



.....  
**Dušan Totek**  
Chief Designer

**Contact address:** ZLIN AIRCRAFT a.s.  
ZLIN SERVICE  
765 81 Otrokovice  
Czech Republic