

MANDATORY SERVICE BULLETIN Z 42/58a

Technical content of the document is approved
on the basis of DOA Approval No. EASA.21J.110

1. **DATE:** January 27, 2010
2. **APPLICABLE TO:** All Z 42, Z 42M, Z 42MU aircraft.
3. **REASON:** Substitution of taxi and landing lights
4. **ACTIONS REQUIRED:** Pertinent revision of accompanying documentation - supplementation of the Directive for replacement of lights
5. **ACCOMPLISHMENT:** Immediately after receipt of this bulletin
6. **PERFORMED BY:** Operator/owner
7. **COSTS COVERED BY:** Operator/owner
8. **PROCEDURES:**
 - a) In Repair Manual of the Z 42, Z 42M, Z 42MU aircraft - czech version:
 - remove old pages: 1, 3, 211, 212
 - insert new pages of Revision No. 17 with date of issue 14. 12. 2009
 - note this revision into the Log of Revision
9. **MATERIAL:** New pages of accompanying documentation (see Enclosure)
10. **ENCLOSURES:** New pages of Z 42, Z 42M, Z 42MU aircraft Repair Manual: 1, 3, 211, 212, 341



.....
Dušan Totek
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
ZLIN SERVICE
765 81 Otrokovice
Czech Republic