



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN No. Z 43/29a

1. **MODELS AFFECTED:** All Z 43 aircraft
2. **SUBJECT:** Increased stress of the V 500 P 7900-611 propeller flange, caused by the execution of spins with the engine power, must be prevented.
3. **CORRECTION:**
 1. Prohibition of intentional power on spins.
 2. Replacement of pages in the Airplane Flight Manual.
4. **TIME OF COMPLIANCE:** Immediately after the Bulletin receipt.
5. **CORRECTION PERFORMED BY:** The user.
6. **EXPENSES COVERED BY:** No expenses will arise.
7. **NECESSARY MATERIAL:** New pages of the Z 43 AFM dated from August 31, 1995 are enclosed to this Bulletin.
8. **PROCEDURE:** Replace original pages by the new ones and enter this revision into the Record of revisions.
9. **THIS BULLETIN IS EFFECTIVE FROM THE DATE OF APPROVAL BY THE CIVIL AVIATION INSPECTORATE.**
10. **ENCLOSURES:** New pages of the Z 43 AFM:
 - a) for aircraft to S/N 084: english AFM version: 19/20, 33/34
german AFM version: 17/18, 31/32
russian AFM version: 19/20, 31/32
 - b) for aircraft from S/N 085: french AFM version:
0-5, 2-9/2-10, 4-15/4-16

Ing. Antonín Partika

.....
Manufacturer's
Representative

Ing. Milan Vyhnálek

.....
CAI Representative

23. 11. 95
.....
Date of approval by the CAI

CONTACT ADDRESS: ZLIN AIRCRAFT a.s.
ZLIN Service
765 81 OTROKOVICE
CZECH REPUBLIC