

MANDATORY SERVICE BULLETIN Z 242L/62a

SAFETY RELATED

Technical content of the document approved
by the EASA Nr. 10045759

- 1. DATE:** June 1, 2013
- 2. MODEL AFFECTED:** All Z 242L aircraft.
- 3. SUBJECT:** Change of airworthiness limitations in aircraft accompanying documentation on the basis of approval new “aerobatic” wings of the Z 242 L aircraft.
- 4. CORRECTION:** Pertinent revision of Z 242L aircraft accompanying documentation.
NOTE:
Conditions for installation of new “aerobatic” wings on the new aircraft or for aircraft’s in operation will be issued by the Information Service Bulletin Z 242L/24b.
- 5. TIME OF COMPLIANCE:** Immediately after receipt of this bulletin
- 6. PERFORMED BY:** Operator/owner.
- 7. COSTS COVERED BY:** No will arise.
- 8. PROCEDURES:**
- a) In Maintenance Manual of the Z 242L, Vol. I (Doc. No. 003.021.1- czech version:
 - remove old pages: 0-3, 0-4, 0-6, 5-5, 5-6, 5-7, 5-8, 5-9, 5-10, 5-11, 5-12, 9-1, 9-2, 9-3, 9-4, 9-5, 9-6
 - insert new pages of Revision No. 20 with date of issue 1.6.2013 (see Enclosure).
 - note this revision into the List of Revisions

- b) In Maintenance Manual of the Z 242L, Vol. I
(Doc. No. 003.022.1 - english version:
remove old pages: 0-3, 0-4, 0-6, 5-5,
5-6, 5-7, 5-8, 5-9, 5-10, 5-11, 5-12, 9-1, 9-2,
9-3, 9-4, 9-5, 9-6
– insert new pages of Revision No. 20 with date
of issue 1.6.2013 (see Enclosure).
– note this revision into the List of Revisions
- c) In Maintenance Manual of the Z 242L, Vol. II
(Doc. No. 003.031.1- czech version:
– remove old pages: 0-3, 0-7, 1-9, 1-10, 1-11,
1-12, 1-13, 1-14, 1-15, 1-16, 1-17, 1-18
– insert new pages of Revision No. 10 with date
of issue 1.6.2013 (see Enclosure).
– note this revision into the List of Revisions
- d) In Maintenance Manual of the Z 242L, Vol. II
(Doc. No. 003.032.1 - english version:
remove old pages: 0-3, 0-7, 1-9, 1-10, 1-11,
1-12, 1-13, 1-14, 1-15, 1-16, 1-17, 1-18
– insert new pages of Revision No. 9 with date of
issue 1.6.2013 (see Enclosure).
– note this revision into the List of Revisions.
- e) In Flight Manual of the Z 242L,
(Doc. No. 003.011.1 – czech version:
– remove old pages: 0-5, 0-7, 2-9
– insert new pages of Revision No. 1 with date of
issue 1.6.2013 (see Enclosure).
– note this revision into the List of Revisions.
- f) In Flight Manual of the Z 242L,
(Doc. No. 003.012.1 – english version:
– remove old pages: 0-5, 0-7, 2-9
– insert new pages of Revision No. 1 with date of
issue 1.6.2013 (see Enclosure).
– note this revision into the List of Revisions.

**9. NECESSARY
MATERIAL:**

New pages of accompanying documentation (see
Enclosure)

10. ENCLOSURES:

New pages of Maintenance Manual of the Z 242L,
Vol. I (Doc. No. 003.021.1) - czech version:
0-3, 0-4, 0-6, 5-5, 5-6, 5-7, 5-8, 5-9, 5-10, 5-11, 5-12,
9-1, 9-2, 9-3, 9-4, 9-5, 9-6, 9-7, 9-8

New pages of Maintenance Manual of the Z 242L,
Vol. I (Doc. No. 003.022.1) - english version:
0-3, 0-4, 0-6, 5-5, 5-6, 5-7, 5-8, 5-9, 5-10, 5-11, 5-12,
9-1, 9-2, 9-3, 9-4, 9-5, 9-6, 9-7, 9-8

New pages of Maintenance Manual of the Z 242L,
Vol. II (Doc. No. 003.031.1) - czech version:
0-3, 0-7, 1-9, 1-10, 1-11, 1-12, 1-13, 1-14, 1-15, 1-16,
1-17, 1-18

New pages of Maintenance Manual of the Z 242L,
Vol. II (Doc. No. 003.032.1) - english version:
0-3, 0-7, 1-9, 1-10, 1-11, 1-12, 1-13, 1-14, 1-15, 1-16,
1-17, 1-18

New pages of Flight Manual of the Z 242L,
(Doc. No. 003.011.1) - czech version:
0-5, 0-7, 2-9

New pages of Flight Manual of the Z 242L,
(Doc. No. 003.012.1) - english version:
0-5, 0-7, 2-9



.....
Ing. Dušan Totek
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
765 02 Otrokovice
Česká republika
www.zlinaircraft.eu