



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlinservice@zlinaircraft.eu
http://www.zlinaircraft.eu

MANDATORY

**SERVICE
BULLETIN**

THE MANDATORY SERVICE BULLETIN Z 142C/9a - REV. 1

(Supersedes Mandatory Service Bulletin Z 142C/9a
dated January 13, 1995)

1. **MODELS AFFECTED:** All manufactured Z 142C aircraft.
2. **SUBJECT:** Results of the review of the rigging measurements and the in-flight checks of the Z 142C and Z 242L fleet.
3. **CORRECTION:**
 - 3.1 The change of permissible tolerances of rigging, as determined in the Levelling/Rigging Record No. 6.901-P, enclosed in the Z 142C Maintenance Manual Vol II. and in the new aircraft documents file.
 - 3.2 Completion of the levelling-rigging procedure carried-out during airplane operation (e.g. at Type B or C Inspections).
4. **TIME OF COMPLIANCE:**

Corr. 3.1. - immediately after receipt of this Bulletin.

Corr. 3.2. - at each levelling/rigging procedure in operation.
5. **CORRECTION PERFORMED BY:** The user
6. **EXPENSES COVERED BY:** No expenses arise
7. **PROCEDURE:**
 - 7.1 The Z 142C Maintenance Manual Vol.II. :
 - a) Remove old pages: 0-3/0-4; 0-5; 0-7; 6-1/6-2; 6-109/6-110; 6-111/6-112; 6-113.
 - b) Insert new revised pages: 0-4; 6-1/6-2; 6-110; 6-111/6-112 dated Rev. Jan 9, 1995 and 0-3; 0-5; 0-7; 6-109; 6-113 dated Rev. Mar 20, 1995.

c) Enter the Revision into the "Log of Revisions" page No. O-7.

7.2. a) Observe the Levelling / Rigging procedure as described in the MD 6.901 enclosed in the Z 142C Maintenance Manual Vol. II.

b) Check that measured rigging values comply with the maximum tolerances as determined in the "Aircraft Levelling/Rigging Record" 6.901-P.

c) In case of exceeding the determined tolerances contact the Manufacturer for decision on further procedure.


8. MATERIAL:


Necessary new pages of the Z 142C Maintenance Manual Vol. II. are enclosed to this Bulletin.

9. THIS REVISION OF THE SERVICE BULLETIN IS EFFECTIVE SINCE THE DATE OF IT'S APPROVAL BY THE CAI OF CR.

10. ENCLOSURES:

New revised pages of the Z 142C MM II, No. O-4; 6-1/6-2; 6-110; 6-111/6-112 dated Rev. Jan 9, 1995 and O-3; O-5; O-7; 6-109; 6-113 dated Rev. Mar 20, 1995.


.....
Manufacturer's Representative


.....
CAI Representative

20.4. 1995
.....
Date