



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN No. Z 143L / 12a

Engineering Aspects are CAI
of the Czech Republic
Approved

1. DATE: December 5, 1996
2. MODELS AFFECTED: All Z 143L airplanes.
3. SUBJECT: Design modifications from S/N 0015 incl. and correction of formal failures in the Z 143L Airplane Flight Manual and in the Z 143L Maintenance Manual - Vol.I.
4. CORRECTION: Replacement of pages in the Z 143L AFM and in the Z 143L MM - Vol.I.
5. TIME OF COMPLIANCE: Immediately after receipt of this Bulletin.
6. CORRECTION PERFORMED BY: The user.
7. EXPENSES COVERED BY: No expenses arise.
8. PROCEDURE:

Replace affected old pages in the Z 143L AFM and in the Z 143L MM - Vol.I with the new ones which are enclosed to this Bulletin. Enter this revision into the Log of Revisions. Write down Serial No. and Registration Mark of appropriate airplane on the new title page (0-1) of the Flight Manual. Invalidate old pages.

 - 8.1. Airplane Flight Manual:
 - 8.1.1 The Czech version, Doc. No. 005.011
New pages marked REVIZE č. 6 (7.11.1996):
0-1, 0-9, 0-10, 0-11, 0-14, 6-24, 7-7, 7-8,
7-9, 7-10, 7-39, 8-9, 8-9a, 8-9b, 8-10.
 - 8.1.2 The English version, Doc. No. 005.012
New pages marked REVISION No. 6 (Nov 7, 1996):
0-1, 0-9, 0-10, 0-11, 0-15, 2-15, 6-24, 7-7,
7-8, 7-9, 7-10, 7-41, 7-42, 8-9a, 8-9b, 8-10.
 - 8.1.3 The US version, Doc. No. 005.012.US
New pages marked REVISION No. 1 (Nov 7, 1996):
0-1, 0-9, 0-10, 0-11, 0-14, 6-24, 7-7, 7-8,
7-9, 7-10, 7-41, 7-42, 8-9a, 8-9b, 8-10.

8.2. Maintenance Manual, Vol.I:

8.2.1 The Czech version, Doc. No. 005.021
New pages marked REVIZE č. 6 (4.11.1996):
0-3, 0-4, 0-6, 2-2, 2-24, 2-25, 2-26, 2-27,
2-27a, 2-27b.

8.2.2 The English version, Doc. No. 005.022
New pages marked REVISION No. 6 (Nov 4, 1996):
0-3, 0-8, 2-2, 2-24, 2-25, 2-26, 2-27, 2-27a,
2-27b.

9. NECESSARY
MATERIAL:

New pages of AFM and MM - Vol.I will be
delivered together with this Bulletin by the
Manufacturer.

10. ENCLOSURES:

New pages of AFM and MM - Vol.I according to
Sect. 8 of this Bulletin.



Dipl.Eng. František Tížek

Manufacturer s Representative