



**ZLIN AIRCRAFT a.s.**  
Letiště 1578, 765 81 Otrokovice,  
Czech Republic  
e-mail: [zlin-service@zlinaircraft.eu](mailto:zlin-service@zlinaircraft.eu)  
<http://www.zlinaircraft.eu>

**MANDATORY**

**SERVICE  
BULLETIN**

**MANDATORY SERVICE BULLETIN Z 143L/14a**

Engineering Aspects are CAI  
of the Czech Republic Approved

1. DATE: April 17, 1997
2. MODELS  
AFFECTED: All ZLIN 143L airplanes.
3. SUBJECT:
  - 3.1 The aircraft from S/N 0023 are equipped with the measuring system of the fuel quantity in the main fuel tanks in the whole range. Installation of the fuel level gauges on the main tanks closures has been cancelled.
  - 3.2 Installation of the FS 4400 anticollision beacon with interference elimination (because of finishing the production of the Whelen WRML beacon).
  - 3.3 Correction of formal failures in the Z 143L Maintenance Manual - Vol.I.
4. CORRECTION: Revision of the Z 143L Maintenance Manual - Vol.I.
5. TIME OF  
COMPLIANCE: Immediately after receipt of the bulletin.
6. CORRECTION  
PERFORMED BY: User.
7. EXPENSES  
COVERED BY: No expenses arise.
8. PROCEDURE: Replace affected old pages in the Z 143L MM - Vol.I with the new ones which are enclosed to this bulletin:
  - 8.1 The Czech version, Doc. No. 005.021  
New pages marked REVIZE č. 7 (25.2.1997):  
0-1, 0-3, 0-4, 0-6, 1-10, 1-12, 1-13, 1-14,  
2-2, 2-25, 2-26, 2-27, 2-27a, 2-27b, 2-56,  
2-57, 2-57a, 2-58, 2-59, 2-59c, 2-59d, 3-5,  
3-7, 3-10, 5-7, 5-27.
  - 8.2 The English version, Doc. No. 005.022  
New pages marked REVISION No. 7 (Feb 25, 1997):  
0-1, 0-3, 0-4, 0-8, 1-11, 1-13, 1-14, 2-2,  
2-25, 2-26, 2-27, 2-27a, 2-27b, 2-58, 2-59,  
2-59a, 2-60, 2-61, 2-61c, 2-61d, 3-5, 3-7,  
3-10, 5-7, 5-25.

Mandatory Service Bulletin  
No. Z 143L/14a

Enter this revision into the Log of Revisions.  
Write down Serial No. and Registration Mark of  
appropriate airplane on the new title page  
(0-1).

9. **NECESSARY MATERIAL:** New pages of MM - Vol.I will be delivered together with this bulletin by the Manufacturer.
10. **ENCLOSURES:** New pages MM - Vol.I according to Sect. 8 of this bulletin.

  
Dipl.Eng. Josef Kolář

Manufacturer's Representative

Contact address: **ZLIN AIRCRAFT a.s.**  
ZLIN Service  
765 81 OTROKOVICE  
CZECH REPUBLIC