



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY BULLETIN Z 143L/26a

Engineering Aspect are
CAA Approved

- 1. DATE:** July 9, 2002
- 2. MODEL AFFECTED:** All Z 143L aircraft.
- 3. SUBJECT:**
- 3.1. Change of the fuel low level measuring from S/N 0053 inclusive.
 - 3.2. Check list supplementing with S-TEC system 55 Autopilot inspection.
- 4. CORRECTION:** In the Z 143L Airplanes Flight Manual (Doc. No. 005.011 - czech version), (Doc. No. 005.012 - english version), (Doc. No. 005.012US - US version) and Z 143L Airplanes Maintenance Manual (Doc. No. 005.021.1 - czech version), (Doc. No. 005.022.1 - english version) replace pages, which are included as an Enclosure of this Bulletin.
- 5. TIME OF COMPLIANCE:** Immediately after receipt of Bulletin.
- 6. CORRECTION PERFORMED BY:** Operator.
- 7. EXPENSES COVERED BY:** No expenses will arise.
- 8. PROCEDURE:**
- a) **In the Z 143L Airplane Flight Manual** (Doc. No. 005.011 - czech version):
 - remove old pages: 0-1, 0-9, 0-10, 0-15, 2-9a, 3-12
 - insert new pages marked with Revision No. 9, 9.7.2002 - see Enclosure
 - note this revision into the List of Revisions.
 - b) **In the Z 143L Airplane Flight Manual** (Doc. No. 005.012 - english version):
 - remove old pages: 0-1, 0-9, 0-10, 0-15, 2-9b, 3-13
 - insert new pages marked with Revision No. 9, Jul. 9, 2002 - see Enclosure
 - note this revision into the List of Revisions.
 - c) **In the Z 143L Airplane flight Manual** (Doc. No. 005.012US - US version):
 - remove old pages: 0-1, 0-9, 0-10, 0-14, 2-9b, 3-13
 - insert new pages marked with Revision No. 4, Jul. 9, 2002 - see Enclosure
 - note this revision into the List of Revisions.
 - d) **In the Z 143L Airplane Maintenance Manual** (Doc. No. 005.021.1 - czech version):
 - remove old pages: 01-11, 01-12, 01-15, 01-17, 01-26, 01-26A, 01-34, 05-20, 24-19, 28-21, 28-28, 28-29, 91-strana 1, 91-3A, 91-4, 91-5, 91-9A, 91-15B, 91-24E, 91-25E
 - insert new pages marked with Revision No. 5, 2002-07-09 - see Enclosure
 - note this revision to the List of Revisions.

- e) **In the Z 143L Airplane Maintenance Manual** (Doc. No. 005.022.1 - english version):
- remove old pages: 01-11, 01-12, 01-15, 01-17, 01-26, 01-26A, 01-34, 05-20, 24-19, 28-21, 28-28, 28-29, 91-page 1, 91-3A, 91-4, 91-5, 91-9A, 91-15B, 91-24E, 91-25E
 - insert new pages marked with Revision No. 5, 2002-07-09 - see Enclosure
 - note this revision into the List of Revisions.

9. NECESSARY MATERIAL: New pages of the Z 143L Airplanes Flight Manual and Z 143L Airplanes Maintenance Manual (see Enclosure).

10. ENCLOSURE:

New pages of the Z 143L Airplane flight Manual (Doc. No. 005.011 - czech version):
0-1, 0-9, 0-10, 0-15, 2-9a, 3-12.

New pages of the Z 143L Airplane Flight Manual (Doc. No. 005.012 - english version):
0-1, 0-9, 0-10, 0-15, 2-9b, 3-13.

New pages of the Z 143L Airplane Flight Manual (Doc. No. 005.012US - US version):
0-1, 0-9, 0-10, 0-14, 2-9b, 3-13.

New pages of the Z 143L Airplane Maintenance Manual (Doc. No. 005.021.1 - czech version):
01-11, 01-12, 01-15, 01-17, 01-26, 01-26A, 01-34, 05-20, 24-19, 28-21, 28-28, 28-29, 91-page 1, 91-3A, 91-4, 91-5, 91-4A, 91-5A, 91-9A, 91-15B, 91-24E, 91-25E, 91-24F, 91-25F, 91-24G, 91-25G.

New pages of the Z 143L Airplane Maintenance Manual (Doc. No. 005.022.1 - english version):
01-11, 01-12, 01-15, 01-17, 01-26, 01-26A, 01-34, 05-20, 24-19, 28-21, 28-28, 28-29, 91-page 1, 91-3A, 91-4, 91-5, 91-4A, 91-5A, 91-9A, 91-15B, 91-24E, 91-25E, 91-24F, 91-25F, 91-24G, 91-25G.



.....
Ing. Dušan Totek
Chief Designer

CONTACT ADDRESS: **ZLIN AIRCRAFT a.s.**
Obchodne-technicke sluzby
765 81 Otrokovice
Czech Republic