



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 143L/30a

Technical content of the document approved
on the basis of DOA Approval No. EASA.21J.110

- 1. DATE:** April 10, 2007

- 2. MODEL AFFECTED:** All Z 143L aircraft with AMU 1 acceleration Monitoring Unit installed.

- 3. SUBJECT:** The Methods of data processing procedure for AMU 1.01 Acceleration Monitoring Unit on the aircraft of Z 43 serie have been revised on the basis of the Methods of data processing procedure for AMU 1.01 Acceleration Monitoring Unit on the aircraft of Z 42 series.

- 4. CORRECTION:** Issue of revised Methods of Data Processing Procedure for AMU 1.01 Acceleration Monitoring Unit for aircraft of Z 43 series.

- 5. TIME OF COMPLIANCE:** Immediately after receipt of this bulletin.

- 6. PERFORMED BY:** Operator.

- 7. COSTS COVERED BY:** No will arise.

- 8. PROCEDURES:**
Replace old Method of data processing procedure for AMU 1.01 Acceleration Monitoring Unit with the new marked by: Revision No. 1 with date April 10, 2007 (see Enclosure).

Cancel old Method of data processing procedure for AMU 1.01 Acceleration Monitoring Unit.

9. NECESSARY MATERIAL:

Method of data processing procedure for AMU 1.01
Acceleration Monitoring Unit for aircraft of Z 43 series in
Czech and English language (see Enclosure).

10. ENCLOSURES:

Method of data processing procedure for AMU 1.01
Acceleration Monitoring Unit for aircraft of Z 43 series
– Czech version: DOC.No.Z43.AMU1.091
+ form Z143L-AMU1/1; Z143L-AMU1/2

Method of data processing procedure for AMU 1.01
Acceleration Monitoring Unit for aircraft of Z 43 series
– English version: DOC.No.Z43.AMU1.092
+ form Z143L-AMU1/1; Z143L-AMU1/2



.....
Dušan Totek
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
ZLIN Service
765 81 Otrokovice
Czech Republic