



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 143L/5a

1. MODELS AFFECTED: All Z 143L aircraft
2. SUBJECT:
 - 2.1 Change of "STALLWARN. FAILURE" annunciator on annunciator lights display the text and colour of which do not correspond to its function.
 - 2.2 Change of IFR DAY/NIGHT placard (if used) for IFR without any differentiation (new version of FAR Part 91).
 - 2.3 Revision of the Flight Manual with the aim of removing formal mistakes and changes following from the aircraft certification in FRG.
3. CORRECTION:
 - 3.1 Replace the present yellow annunciator "STALLWARN. FAILURE" on the annunciator lights display for a new one of white colour marked "STALLWARN. INACTIVE" that is enclosed to this Bulletin.
 - 3.2 Replace IFR DAY/NIGHT placard (if used) for IFR placard that is enclosed to this Bulletin.
 - 3.3 Replace the present Flight Manual [Doc. No. 005.012(ENGLISH), 005.011(CZECH)] Revision No. 2 for a new one marked as Revision No. 3 that is enclosed to this Bulletin.
4. TIME OF COMPLIANCE: Immediately after receipt of this Bulletin.
5. CORRECTION PERFORMED BY: The user.
6. EXPENSES COVERED BY: No expenses arise.
7. PROCEDURE:
 - 7.1 Using a small screwdriver take out the present yellow annunciator "STALLWARN. FAILURE" and place annunciator "STALLWARN. INACTIVE" of white colour in its place.
Check for function (having switched on the master switch and circuit switches the light must be "ON" on the ground).
 - 7.2 Replace IFR DAY/NIGHT placard (if used) for IFR placard.


- 7.3 Replace the Flight Manual, Revision No. 2 for the Flight Manual, Revision No. 3. Write S/N and registration mark of your aircraft on the title page (0-1) of the Flight Manual. "Transfer" the data on basic empty weight of your aircraft from the Flight Manual Rev. No. 2 into "Form", Subsection 6.2 of the Flight Manual, Revision No. 3. Incorporate Supplements of the AFM Rev.No.2 (if used) into Section No.9 of the AFM Rev.No.3. Invalidate the Flight Manual, Revision No. 2.

8. NECESSARY MATERIAL:


- 8.1 Annunciator of white colour "STALLWARN. INACTIVE"
8.2 IFR placard
8.3 Flight Manual, Doc. No. 005.012 - Revision No. 3.

9. THIS BULLETIN IS EFFECTIVE FROM THE DATE OF ITS APPROVAL BY THE CIVIL AVIATION INSPECTORATE.

10. ENCLOSURE: 10.1 Annunciator of white colour "STALLWARN. INACTIVE"
10.2 IFR placard
10.3 Flight Manual - Doc. No. 005.012 - Rev. No. 3.


Ing. František Tížek

.....
Manufacturer's
Representative


Ing. Milan Vyhnašek

.....
CAI Representative

13. 5. 1996
.....
Date of CAI Approval

CONTACT ADDRESS: **ZLIN AIRCRAFT a.s.**
ZLIN SERVICE
765 81 Otrokovice
CZECH REPUBLIC