



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 143LSi/1a

Technical content of the document approved
on the basis of DOA Approval No. EASA.21J.110

1. **DATE:** September 11, 2006
2. **MODEL AFFECTED:** All Z 143LSi aircraft.
3. **SUBJECT:** Z 143L / Z 143LSi aircraft design modification applicable from S/N 0046 incl. and permission of max. six-turn spin performance in Utility category according to FAR Part 23.3 (b)(1) regulation.
4. **CORRECTION:** Relevant revision of Flight manual of the Z 143LSi aircraft.
5. **TIME OF COMPLIANCE:** Immediately after receipt of this bulletin.
6. **PERFORMED BY:** Operator.
7. **COSTS COVERED BY:** No will arise.
8. **PROCEDURES:**
 - a) In the Flight Manual of the Z 143LSi aircraft; DOC. No. Si 005.011
– Czech version:
 - remove old pages: 0-1; 0-8; 0-9; 0-10; 0-12; 2-10; 2-15; 3-13; 3-14; 3-15; 3-16; 3-17; 3-18; 4-28; 4-29; 7-2; 7-27; 7-28; 7-29; 7-33
 - insert new pages marked with Revision No. 1 with date 2006-08-03 (see Enclosure)
 - note this revision into the List of revisions.
 - b) In the Flight Manual of the Z 143LSi aircraft; DOC. No. Si 005.012
– English version:
 - remove old pages: 0-1; 0-8; 0-9; 0-10; 0-12; 2-10 2-15; 3-13; 3-15; 4-28; 4-29; 7-2; 7-27; 7-28; 7-29; 7-33
 - insert new pages marked with Revision No. 1 with date 2006-08-03 (see Enclosure)
 - note this revision into the List of revisions.

9. NECESSARY MATERIAL:

New pages of Flight Manual of the Z 143LSi aircraft; DOC. No. Si 005-011 – Czech version (see Enclosure).


New pages Flight Manual of the Z 143LSi aircraft; DOC. No. Si 005-012 – English version (see Enclosure).

10. ENCLOSURE:

New pages of Flight Manual of the Z 143LSi aircraft; DOC. No. Si 005.011 – Czech version:
0-1; 0-8; 0-9; 0-10; 0-12; 2-10; 2-15; 3-13; 3-14; 3-15; 3-16; 3-17; 3-18; 4-28; 4-29; 7-2; 7-7A; 7-7B; 7-8A; 7-8B; 7-27; 7-27A; 7-27B; 7-28; 7-29; 7-33.

New pages of Flight Manual of the Z 143LSi aircraft; DOC. No. Si 005.012 – English version:
0-1; 0-8; 0-9; 0-10; 0-12; 2-10; 2-15; 3-13; 3-15; 4-28; 4-29; 7-2; 7-7A; 7-7B; 7-8A; 7-8B; 7-27; 7-27A; 7-27B; 7-28; 7-29; 7-33.

SIGNED:



Dušan Totek
Chief Designer

Contact address:

ZLIN AIRCRAFT a.s.

ZLIN Service
765 81 Otrokovice
Czech Republic