Download date: 14.03.2013



ZLIN AIRCRAFT a.s.

Letiště 1578, 765 81 Otrokovice, Czech Republic

e-mail: zlinservice@zlinaircraft.eu http://www.zlinaircraft.eu



THE MANDATORY SERVICE BULLETIN Z 242L/13a - REV. 1

(Supersedes Mandatory Service Bulletin Z 242L/13a dated January 13, 1995)

1. MODELS AFFECTED:

All manufactured Z 242L aircraft.

2. SUBJECT:

Results of the review of the rigging measurements and the in-flight checks of the Z 242L and Z 142C fleet.

3. CORRECTION:

- 3.1 The change of permissible tolerances of rigging, as determined in the Levelling/Rigging Record No. 6.901-P, enclosed in the Z 242L Maintenance Manual Vol II. and in the new aircraft documents file.
- 3.2 Completion of the levelling-rigging procedure carried-out during airplane operation (e.g. at Type B or C Inspections).
- 4. TIME OF COMPLIANCE:

Corr. 3.1. - immediately after receipt of this Bulletin.

Corr. 3.2. - at each levelling/rigging procedure in operation.

5. CORRECTION PERFORMED BY: The user

6. EXPENSES COVERED BY:

No expenses arise

7. PROCEDURE:

- 7.1 The Z 242L Maintenance Manual Vol. II, Doc. No. 003.032:
 - a) Remove old pages: 0-3/0-4; 0-5; 0-7; 6-1; 6-105/6-106; 6-109/6-110; 6-111/6-112.
 - b) Insert new revised pages: 0-4; 6-1; 6-106; 6-109; 6-111 dated Rev. Jan 9, 1995 and 0-3; 0-5; 0-7; 6-105; 6-110; 6-112 dated Rev. Mar 20, 1995.

- c) Enter the Revision into the "Log of Revisions" page No. 0-7.
- 7.2. a) Observe the Levelling / Rigging procedure as described in the MD 6.901 enclosed in the Z 242L Maintenance Manual Vol. II.
 - b) Check that measured rigging values comply with the maximum tolerances as determined in the "Aircraft Levelling/Rigging Record" 6.901-P.
 - c) In case of exceeding the determined tolerances contact the Manufacturer for decision on further procedure.

8. MATERIAL:

Necessary new pages of the Maintenance Manual Vol. II. are enclosed to this Bulletin.

- 9. THIS REVISION OF THE SERVICE BULLETIN IS EFFECTIVE SINCE THE DATE OF IT'S APPROVAL BY THE CAI OF CR.
- 10. ENCLOSURES:

New revised pages of the Z 242L MM II, No. 0-4; 6-1; 6-106; 6-109; 6-111 dated Rev. Jan 9, 1995 and 0-3; 0-5; 0-7; 6-105; 6-110; dated Rev. Mar 20, 1995.

Manufacturer's Representative Representative