



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY BULLETIN Z 242L/41a

Engineering aspect
CAA approved

- 1. DATE:** February 26, 2002
- 2. MODEL AFFECTED:** All aircraft ZLIN 242 L with HARTZELL HC-C3YR-4BF/FC 6890 propeller equipped.
- 3. SUBJECT:** In the supplements No. 3 of the Z 242 L aircraft Flight manual was implementation within the Engine check the missing of adjustment of propeller.
- 4. CORRECTION:** In the supplements No. 3 of the Z 242 L aircraft Flight manual replace primary pages behind the pages which are included as an Enclosure of this bulletin.
- 5. TIME OF COMPLIANCE:** Immediately after receipt of bulletin
- 6. CORRECTION PERFORMED BY:** Operator's
- 7. EXPENSES COVERED BY:** No expenses will arise
- 8. PROCEDURE:**
- a) IN THE SUPPLEMENT No. 3 OF THE Z 242 L AIRCRAFT FLIGHT MANUAL (DOC.No. 003.011) - czech version**
 - remove old pages: 1 z 10, 2 z 10, 7 z 10
 - insert new pages with marked REVIZE č. 1 with date 26.2.2002 - see Enclosure
 - b) IN THE SUPPLEMENT No. 3 OF THE Z 242 L AIRCRAFT FLIGHT MANUAL (DOC.No. 003.012) - english version**
 - remove old pages: 1 of 10, 2 of 10, 7 of 10
 - insert new pages with marked REVISION No. 1 with date Feb. 26, 2002 - see Enclosure
- 9. NECESSARY MATERIAL:** New pages of the Supplement No. 3 and 17 of the Z 242 L aircraft Flight manual (see Enclosure).

10. ENCLOSURE:

New pages of the Supplement No. 3 of the Z 242L aircraft Flight manual
(DOC.No. 003.011) - czech version
1 z 10, 2 z 10, 7 z 10

New pages of the Supplement No. 3 of the Z 242L aircraft Flight manual
(DOC.No. 003.012) - english version
1 of 10, 2 of 10, 7 of 10



.....
Ing. Dušan Totek
Chief designer

Contact adress:

ZLIN AIRCRAFT a.s.
Obchodne-technicke sluzby
765 81 Otrokovice
Czech Republic