



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 242L/47a

Technical content of the document approved
on the basis of DOA Approval No. EASA.21J.110

- 1. DATE:** June 20, 2006
- 2. MODEL AFFECTED:** All Z 242L aircraft.
- 3. SUBJECT:** Formal arrangements of accompanying technical documentation on the basis of operator's notice from aircraft operation.
- 4. CORRECTION:** Pertinent revision of accompanying technical documentation.
- 5. TIME OF COMPLIANCE:** Immediately after receipt of this bulletin.
- 6. PERFORMED BY:** Operator.
- 7. COSTS COVERED BY:** No will arise.
- 8. PROCEDURES:**
 - a) In the Maintenance Manual of the Z 242L aircraft – Vol. I., DOC.No.003.021.1 – Czech version:
 - remove old pages: 0-3; 0-4; 0-6; 2-15; 3-3; 4-13; 5-5; 5-18
 - insert new pages of Revision No. 16 with date 20. 6. 2006 (see Enclosure)
 - note this revision into the List of revisions
 - b) In the Maintenance Manual of the Z 242L aircraft – Vol. II., DOC.No.003.031.1 – Czech version:
 - remove old pages: 0-3; 0-4; 0-5; 0-7; 6-1; 6-59; 6-119; 7-27
 - insert new pages of Revision No. 7 with date 20. 6. 2006 (see Enclosure)
 - note this revision into the List of revisions
 - c) In the Maintenance Manual of the Z 242L aircraft – Vol. I., DOC.No.003.022.1 – English version:
 - remove old pages: 0-3; 0-4; 0-6; 2-15; 3-3; 4-13; 5-5; 5-10; 5-18
 - insert new pages of Revision No. 16 with date Jun 20, 2006 (see Enclosure)
 - note this revision into the List of revisions

MANDATORY SERVICE BULLETIN Z 242L/47a

- d) In the Maintenance Manual of the Z 242L aircraft – Vol. II., DOC.No.003.032.1 – English version:
- remove old pages: 0-3; 0-4; 0-5; 0-7; 6-1; 6-59; 6-119; 7-27
 - insert new pages of Revision No. 6 with date Jun 20, 2006 (see Enclosure)
 - note this revision into the List of revisions

9. NECESSARY MATERIAL:

New pages of accompanying technical documentation (see Enclosure).

10. ENCLOSURE:

- a) New pages of Maintenance Manual of the Z 242L aircraft – Vol. I., DOC.No.003.021.1 – Czech version:
0-3; 0-4; 0-6; 2-15; 3-3; 4-13; 5-5; 5-18
- b) New pages of Maintenance Manual of the Z 242L aircraft – Vol. II., DOC.No.003.031.1 – Czech version:
0-3; 0-4; 0-5; 0-7; 6-1; 6-59; 6-78A; 6-78B; 6-78C; 6-78D; 6-119; 7-27
- c) New pages of Maintenance Manual of the Z 242L aircraft – Vol. I., DOC.No.003.031.1 – English version:
0-3; 0-4; 0-6; 2-15; 3-3; 4-13; 5-5; 5-10; 5-18
- d) New pages of Maintenance Manual of the Z 242L aircraft – Vol. II., DOC.No.003.032.1 – English version:
0-3; 0-4; 0-5; 0-7; 6-1; 6-59; 6-78A; 6-78B; 6-78C; 6-78D; 6-119; 7-27



.....
Dušan Totek
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
ZLIN Service
765 81 Otrokovice
Czech Republic