

MANDATORY SERVICE BULLETIN Z 242L/60a

Technical content of the document is approved
on the basis of DOA Approval No. EASA.21J.110

- 1. DATE:** December 10, 2010
- 2. APPLICABLE TO:** All Z 242L aircraft
- 3. REASON:** Formal changes in accompanying documentation based on comments from operators.
- 4. ACTIONS REQUIRED:** Pertinent revision of Z 242L aircraft accompanying documentation.
- 5. ACCOMPLISHMENT:** Immediately after receipt of this bulletin
- 6. PERFORMED BY:** Operator/owner.
- 7. COSTS COVERED BY:** Operator/owner.
- 8. PROCEDURES:**
 - a) In Maintenance Manual of the Z 242L, Vol. I (Doc. No. 003.021.1) - Czech version:
 - remove old pages: 0-3, 0-4, 0-6, 5-10, 5-12, 5-21, 5-26
 - insert new pages of Revision No. 19 with date of issue 1.11. 2010 (see Enclosure).
 - note this revision into the List of Revisions
 - b) In Maintenance Manual of the Z 242L, Vol. I (Doc. No. 003.022.1) - English version:
 - remove old pages: 0-3, 0-4, 0-6, 5-10, 5-12, 5-21b, 5-26
 - insert new pages of Revision No. 19 with date of issue 1.11. 2010 (see Enclosure).
 - note this revision into the List of Revisions

**9. NECESSARY
MATERIAL:**

New pages of accompanying documentation (see
Enclosure)

10. ENCLOSURES:

New pages of Z 242L aircraft Maintenance Manual,
Vol. I (Doc. No. 003.021.1) - Czech version:
0-3, 0-4, 0-6, 5-10, 5-12, 5-21, 5-26

New pages of Z 242L aircraft Maintenance Manual,
Vol. I (Doc. No. 003.022.1) - English version:
0-3, 0-4, 0-6, 5-10, 5-12, 5-21b, 5-26



.....
Ing. Dušan ToteK
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
ZLIN SERVICE
765 81 Otrokovice
Česká republika