



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

SERVICE BULLETIN Z 43/35a

(Supersedes Service bulletin Z 43/21)

Engineering Aspects are CAI
of the Czech Republic Approved

1. DATE: January 22, 1997
2. MODELS AFFECTED: All Zlin 43 aircraft.
3. SUBJECT: In virtue of operational experiences and residual fatigue test results the service life of the landing gear legs was determined on 6000 landings.
4. CORRECTION: Work the above-mentioned increased service life of the landing gear legs in the accompanying documentation file of the aircraft.
5. CORRECTION PERFORMED BY: Aircraft operator.
6. TIME OF COMPLIANCE: Immediately after this Bulletin receipt.
7. PROCEDURE: Correct by hand data about the landing gear legs service life from 4100 landings on 6000 landings in the accompanying aircraft documentation file.


Josef Kolář

.....
Manufacturer's
Representative

CONTACT ADDRESS: **ZLIN AIRCRAFT a.s.**
ZLIN SERVICE
765 81 Otrokovice
CZECH REPUBLIC