

4.03.2013



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 50M/10a

1. **MODELS AFFECTED:** All Z 50M airplanes.
2. **SUBJECT:** Correction of data concerning engine and propeller inspections and overhauls.
3. **CORRECTION:** Data correction in the airplane accompanying documentation.
4. **TIME OF COMPLIANCE:** Immediately after receipt of this Bulletin.
5. **CORRECTION PERFORMED BY:** Operator.
6. **EXPENSES COVERED BY:** No expenses arise.
7. **NECESSARY MATERIAL:** New pages of Z 50M airplane Technical Manual.
8. **PROCEDURE:**
 1. Replace old pages 0-3, 0-5, 3-29/3-30 with new ones in Technical Manual (and in Maintenance Manual) and make an appropriate entry in the Log of Revisions.
 2. Make the engine and propeller overhauls and inspections within the time intervals specified in the accompanying documentation, revised by this Bulletin.


9. THIS BULLETIN IS EFFECTIVE FROM THE DATE OF APPROVAL BY THE CIVIL AVIATION INSPECTORATE.

10. ENCLOSURES: New pages of Z 50M airplane Technical Manual:
0-3, 0-5, 3-29/3-30.



Dipl.Eng. František Tížek

Moravan, Inc. Otrokovice



Dipl.Eng. Milan Vyhnálek

CAI Prague

October 30, 1996

Date of approval by the CAI

CONTACT ADDRESS:

ZLIN AIRCRAFT a.s.
ZLIN SERVICE
765 81 OTROKOVICE
CZECH REPUBLIC