



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlinservice@zlinaircraft.eu
http://www.zlinaircraft.eu

MANDATORY

**SERVICE
BULLETIN**

Mandatory bulletin Z 50 M/04

1. Subjekt: All the Z 50 M aircraft.
2. Reason: Making more accurate the Flight Manual about the calculated influence of the altitude and temperature on the take-off, rate of climb and landing according to the requirement of FAR §23.1587 (a) (8).
3. Measures: The exchange of the Flight Manual pages according to the point 10 - ENCLOSURES.
4. Measures will be performed: Immediately after bulletin receipt.
5. Performer: The user.
6. Expenses will be covered: They will not arise.
7. Necessary material: The Flight Manual new pages according to the point 10 - ENCLOSURES.
8. Procedure: Replace the Flight Manual original pages with new ones.
9. THE BULLETIN COMES INTO FORCE ON DATE OF APPROVAL BY CAI.
10. Enclosures: New pages of the Z 50 M Flight Manual: 0-5, 5-1, 5-7, 5-8, 5-9.

Ing. Antonín Partika
.....
MORAVAN, Inc. Otrokovice

Ing. Milan Vyhnálek
.....
CAI, Prague

20. 11. 1992

.....
Date of Approval by CAI