

ZLIN AIRCRAFT a.s.

Letiště 1578, 765 81 Otrokovice, Czech Republic

e-mail: zlinservice@zlinaircraft.eu http://www.zlinaircraft.eu



Service Letter No. L29 September 24, 1999

To:

All operators and owners of Zlin 242 L aircraft until (and

inclusive) the S/N 0735

Subject:

Replacement of the hoses of oil system

Referring to the oil system of the aircraft Z 242 L, beginning to the S/N 0736, ZLIN AIRCRAFT a.s. , applies in the production instead of former time-limited rubber hoses MoN 1818.2 the new AE 366 AEROQUIP, which has its lifetime unlimited.

Regarding to all the aircraft until S/N 0735 inclusive: after the lifetime expires, it is necessary to order the new AE 366 AEROQUIP set including to inch-thread connections, reductions and elbows that essential to be removed at the connecting points.

Other details are included within our Catalogue of Spare parts of Z 242 L.

If necessary (by any reason) to change a hose (or part of) separately, the individual order of the hose (including to relevant connections, reductions and elbows) is also possible to apply.

Lubomír Hubený Chief Designer

Contact address:

ZLIN AIRCRAFT a.s.

765 81 Otrokovice, Czech Republic