

ZLIN AIRCRAFT a.s.

Letiště 1578, 765 81 Otrokovice, Czech Republic

e-mail: zlinservice@zlinaircraft.eu http://www.zlinaircraft.eu



MANDATORY SERVICE BULLETIN Z 137T/1a

1. AFFECTED AIRCRAFT: All manufactured Z 137T aircraft up to

S/N 051 incl.

2. SUBJECT: Modification of the operating air speed for the aerial application.

3. CORRECTION: 1. Replacement of placards in the co

Replacement of placards in the cockpit.
Replacement of pages in the Flight Manual.

4. TIME OF COMPLIANCE: Immediately after receipt of this Bulletin.

5. PERFORMED BY: The Operator.

6. EXPENSES COVERED BY: No expenses arise.

7. NECESSARY MATERIAL: The new placard and new pages of FM delivered by the Manufacturer.

8. PROCEDURE:

1. Replace the placard in the cockpit by the new one.

2. Replace original pages of the Flight Manual by the new ones.

9. THE BULLETIN COMES IN FORCE WITHIN 30 DAYS FROM THE DATE OF APPROVAL BY THE CAI OF THE CZECH REPUBLIC.

10. APPENDICES:

New pages of the Flight Manual: 0-5/0-6, 2-11/2-12, 4-19/4-20.

Manufacturer's Representative

Civil Aviation Inspectorate

Dipl.-Ing. Antonín Partika

Dipl.-Ing. Vladimír Příhoda

Date of CAI Approval

June 6, 1994

CONTACT ADRESS:

ZLIN AIRCRAFT a.s.

ZLIN Service 765 81 OTROKOVICE