



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 142/52a

Technical content of the document approved
on the basis of DOA Approval No. EASA.21J.110

1. **DATE:** February 28, 2006
2. **MODEL AFFECTED:** All Z 142 aircraft.
3. **SUBJECT:** Formal arrangements of accompanying technical documentation on the basis of operator's notice from aircraft operation.
4. **CORRECTION:** Pertinent revision of accompanying technical documentation.
5. **TIME OF COMPLIANCE:** Immediately after receipt of this bulletin.
6. **PERFORMED BY:** Operator.
7. **COSTS COVERED BY:** No will arise.
8. **PROCEDURES:**
 - a) In the Z 142 aircraft Flight Manual – Czech version:
 - remove old pages: 1-4; 2-20; 7-4; 7-5
 - insert new pages of Revision with date 28. 2. 2006 (see Enclosure)
 - note this revision into the List of revisions
 - b) In the Z 142 aircraft Flight Manual – English version:
 - remove old pages: 1-4; 2-20; 4-16; 7-4; 7-6
 - insert new pages of revision with date 28. 2. 2006 (see Enclosure)
 - note this revision into the List of revisions
 - c) In the Z 142 aircraft Flight Manual – Germany version:
 - remove old pages: 1-4; 2-20; 7-4; 7-6
 - insert new pages of revision with date 28.2.2006 (see Enclosure)
 - note this revision into the List of revisions

9. NECESSARY MATERIAL:

New pages of accompanying technical documentation (see Enclosure).

10. ENCLOSURE:

- a) New pages of Z 142 aircraft Flight Manual – Czech version: 1-4; 2-20; 7-4; 7-5.
- b) New pages of Z 142 aircraft Flight Manual – English version: 1-4; 2-20; 4-16; 7-4; 7-6.
- c) New pages of Z 142 aircraft Flight Manual – Germany version: 1-4; 2-20; 7-4; 7-6.

SIGNED:



.....
Dušan ToteK
Chief Designer

Contact address:

ZLIN AIRCRAFT a.s.
ZLIN Service
765 81 Otrokovice
Czech Republic