



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY BULLETIN Z 142C/21a

Engineering Aspect are
CAA Approved

- 1. DATE:** January 2, 2001
- 2. MODELS AFFECTED:** All Z 142C aircraft.
- 3. SUBJECT:** In The Maintenance Manual of the Z 142C aircraft, Vol. II (in text further only Maintenance Manual) was to completion of direction for checking of oil installation drop valve.
- 4. CORRECTION:** In The Maintenance Manual replace pages, which are included as an Enclosure of this Bulletin.
- 5. TIME OF COMPLIANCE:** Immediately after receipt of Bulletin.
- 6. CORRECTION PERFORMED BY:** Operator.
- 7. EXPENSES COVERED BY:** No expenses will arise.
- 8. PROCEDURE:** In The Maintenance Manual
- remove old pages: 0-3, 0-4, 0-5, 0-7, 6-1
- insert new pages marked with Rev. with Jan 2,2001 date (see Enclosure).
- note this revision into the List of Revisions
- 9. NECESSARY MATERIAL:** New pages of The Maintenance Manual (see Enclosure).
- 10. ENCLOSURE:** New pages in The Maintenance Manual
0-3, 0-4, 0-5, 0-7, 6-1, 6-98a, 6-98b.

A handwritten signature in blue ink, appearing to read 'Totek'.

.....
Ing. Dušan Totek
Chief Designer

CONTACT ADDRESS: ZLIN AIRCRAFT a.s.
Obchodne technicke sluzby
765 81 Otrokovice
Czech Republic