



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 142 C/29a

Engineering Aspects are
CAA CZ Approved


1. **DATE:** February 28, 2005
2. **MODEL AFFECTED:** All Z 142C aircraft.
3. **SUBJECT:** Implementation of manufacture directive for Check of fuel level gauges and manufacture directive for Check of fuel system leakage.
4. **CORRECTION:** Pertinent revision of accompanying documentation.
5. **TIME OF COMPLIANCE:** Immediately after receipt of bulletin.
6. **PERFORMED BY:** Operator.
7. **COSTS COVERED BY:** No will arise..
8. **PROCEDURES:**
 - a) In the Maintenance Manual of the Z 142 C, Vol. II., Czech version:
 - remove old pages: 0-3; 0-4; 0-5; 0-7; 3-24; 5-5; 5-6; 6-1; 6-96a; 6-96b
 - insert new pages marked with Revision No. 4 with date 28. 2. 2005 (see Enclosure)
 - note this revision into the List of revisions.
 - b) In the Maintenance Manual of the Z 142 C, Vol. II. English version:
 - remove old pages: 0-3; 0-4; 0-5; 0-7; 3-25; 5-6; 6-1; 6-98a; 6-98b
 - insert new pages marked with Revision No. 10 with date Feb. 28, 2005 (see Enclosure)
 - note this revision into the List of revisions.

9. NECESSARY MATERIAL: New pages of accompanying documentation.

10. ENCLOSURE: New pages of Maintenance Manual of the Z 142 C, Vol. II., Czech version:
0-3; 0-4; 0-5; 0-7; 3-24; 5-5; 5-6; 6-1; 6-96a; 6-96b; 6-96c; 6-96d; 6-96e; 6-96f.

New page of Maintenance Manual of the Z 142 C, Vol. II., English version:
0-3; 0-4; 0-5; 0-7; 3-25; 5-6; 6-1; 6-98a; 6-98b; 6-98c; 6-98d; 6-98e; 6-98f.

SIGNED:


.....
Dušan Totecký
Chief Designer

Contact address: **ZLIN AIRCRAFT a.s.**
ZLIN Service
765 81 Otrokovice
Czech Republic