



ZLIN AIRCRAFT a.s.
Letiště 1578, 765 81 Otrokovice,
Czech Republic
e-mail: zlin-service@zlinaircraft.eu
<http://www.zlinaircraft.eu>

MANDATORY

**SERVICE
BULLETIN**

MANDATORY SERVICE BULLETIN Z 143 L/37a-Rev.1
Z 143 LSi/7a-Rev.1

Technical content of the document approved
by the EASA Nr. 0010012020-001

- 1. DATE:** April 6, 2012
- 2. APPLICABLE TO:** All Z 143L and Z 143LSi aircraft
- 3. REASON:** Issue of new version of Z 143L - Z 143LSi Airplane Maintenance Manual (Doc. No. 005.021.2 Czech version) resp. (Doc. No. 005.022.2 English version) with date of issue 2011-02-02.
- 4. ACTIONS REQUIRED:** Issue of new version of Z 143L - Z 143LSi Airplane Maintenance Manual.
Simultaneously with issuing new versions of Maintenance Manual, validity of existing Aircraft Maintenance Manual Z 143 L (Doc. No. 005.021.1 Czech version) or (Doc. No. 005.022.1 English version) with the date of issue 1998-06-30 and Appendix of Maintenance Manual for Z 143 LSi aircraft (Doc. No. Si005.021.1 Czech version) or (Doc. No. Si005.022.1) with date of issue 2002-02-02 is cancelled.
- 5. ACCOMPLISHMENT:** Immediately after receipt of this bulletin
- 6. PERFORMED BY:** Operator/owner.
- 7. COSTS COVERED BY:** Operator/owner.

8. PROCEDURES:

- a) Subscribers of bulletin service:
- Download required manual in PDF format from web site of aircraft manufacturer and print it.
 - Transcribe the aircraft S/N and registration mark from original manual to the title page.
 - Take the supplements No. 1 (Instrument lighting) and No. 2 (Communication and navigation equipment) from Chapter 95 "Supplements" of original manual and insert it to new manual.
 - Also download and print the supplements mentioned in original manual (on the page 95-1 "List of Supplements") and insert them behind the Supplements No. 1 and No. 2.
 - Shred the original Maintenance Manual.
- b) The users that are not subscribers of bulletin service:
- In writing or by e-mail, according to valid price list, order the registered copy of the Maintenance Manual on electronic medium.

9. NECESSARY MATERIAL:

- a) New Maintenance Manual Z 143L – Z 143LSi including Supplements (available for free to the subscribers of bulletin service).
- b) New Maintenance Manual Z 143L – Z 143LSi including Supplements (available for payment to the users that are not subscribers of bulletin service).

10. ENCLOSURES:

N/A



.....
Ing. Dušan Totek
Chief Designer

Contact address: ZLIN AIRCRAFT a.s.
ZLIN SERVICE
765 81 Otrokovice
Czech Republic