



**ZLIN AIRCRAFT a.s.**  
Letiště 1578, 765 81 Otrokovice,  
Czech Republic  
e-mail: [zlin-service@zlinaircraft.eu](mailto:zlin-service@zlinaircraft.eu)  
<http://www.zlinaircraft.eu>

**MANDATORY**

**SERVICE  
BULLETIN**

## **MANDATORY SERVICE BULLETIN Z 43/49a**

Technical content of the document approved  
on the basis of DOA Approval No.  
EASA.21J.110

- 1. DATE:** May 6, 2010
- 2. MODEL AFFECTED:** All Z 43 aircraft operated on the basis of so-called “preliminary operation” in new maintenance system with performance of 100-hour or 1-year inspections (depending on what comes earlier) according to the Z 43 Maintenance Manual (Doc. No. 233.021).
- 3. SUBJECT:** Formal corrections of accompanying documentation,
- 4. CORRECTION:** Relevant revision of Maintenance Manual for the ZLIN 43 Aircraft.
- 5. TIME OF COMPLIANCE:** Immediately after receipt of this Bulletin.
- 6. PERFORMED BY:** Operator.
- 7. COSTS COVERED BY:** No will arise.
- 8. PROCEDURES:**
- a) In the Maintenance Manual for the ZLIN 43 Aircraft (DOC. No. 233.021):
    - remove old pages: Title, 01-5, 01-13, 01-14, 01-15, 01-16, 01-17, 01-18, 01-19, 01-23, 01-24, 01-27, 01-28, 04-3, 05-1, 05-3, 05-5, 05-6, 05-11, 05-16, 05-18, 05-19, 05-21, 05-22, 05-24, 05-25, 05-26, 05-27, 08-5, 08-8, 11-17, 12-7, 12-9, 20-6, 20-14, 20-17, 20-20, 20-24, 20-26, 20-27, 20-30, 20-32, 20-34, 23-4, 23-5, 23-11, 27-4, 27-8, 27-15, 27-19, 27-20, 27-26, 27-32, 31-13, 31-14, 32-5, 32-6, 32-10, 32-11, 32-18, 32-22, 32-57, 34-10, 51-19, 51-52, 52-6, 55-9, 55-10, 55-11, 55-16, 55-21, 57-12, 57-19, 57-29, 61-5, 71-14, 72-10, 79-6, 79-19, 91-12.
    - insert new pages of Revision No. 3 with date 2009-05-12 (see Enclosure).
    - note this revision into the List of Changes.

**9. NECESSARY MATERIAL:** New pages of the Maintenance Manual for the ZLIN 43 Aircraft (see Enclosure).

**10. ENCLOSURE:** New pages of the Maintenance Manual for the ZLIN 43 Aircraft (DOC. No. 233.021):

Title, 01-5, 01-13, 01-14, 01-15, 01-16, 01-17, 01-18, 01-19, 01-23, 01-24, 01-27, 01-28, 04-3, 05-1, 05-3, 05-5, 05-6, 05-6A, 05-6B, 05-11, 05-16, 05-18, 05-19, 05-21, 05-22, 05-24, 05-25, 05-26, 05-27, 08-5, 08-8, 11-17, 12-7, 12-9, 20-6, 20-14, 20-17, 20-20, 20-24, 20-26, 20-27, 20-30, 20-32, 20-34, 23-4, 23-5, 23-11, 27-4, 27-8, 27-15, 27-19, 27-20, 27-26, 27-32, 31-13, 31-14, 32-5, 32-6, 32-10, 32-11, 32-18, 32-22, 32-57, 34-10, 51-19, 51-52, 52-6, 55-9, 55-10, 55-11, 55-16, 55-21, 57-12, 57-19, 57-29, 61-5, 71-14, 72-10, 79-6, 79-19, 91-12.



.....  
**Ing. Dušan Totek**  
Chief Designer

**CONTACT ADDRESS:** ZLIN AIRCRAFT a.s.  
ZLIN Service  
765 81 Otrokovice  
Czech Republic